

Caravan Mover Fault Flowchart V1.4

Written for Carver AR2-1 and Truma M1

Common Problems:

1. On AR2-1: 3 Red Flashes (Short to chassis) signifies that the control PCB needs repair.
2. If the fault is due to poor range, then a repair is required

For Sales & repair of Truma / Carver Mover and heater products see our [website](#)

A&R Electronic Developments Ltd

Unit 14 Littleton Business Park
Littleton Drive
Cannock WS12 4TR
England

Tel: +44 (0)1543 579302
web: www.arelectronics.co.uk
email: rsol@arelectronics.co.uk

