

# Caravan Mover Fault Flowchart V1.3

Written for Carver AR2-1 and Truma M1

## Common Problems:

1. On AR2-1: 3 Red Flashes (Short to chassis) signifies that the control PCB needs repair.
2. If the fault is due to poor range, then a repair is required

For Sales & repair of Truma / Carver Mover and heater products see our [website](#)

A&R Electronic Developments Ltd  
 Unit 5a Key Point  
 Keys Park Road  
 Hednesford  
 Staffs **WS12 2FN**  
 01543 274284 (Mon-Fri 9.00 -5.00)  
 web: [www.arelectronics.co.uk/repairs.htm](http://www.arelectronics.co.uk/repairs.htm)  
 email: [rsol@arelectronics.co.uk](mailto:rsol@arelectronics.co.uk)

